

There is not a

To The Authorized Signatory. Golden International School, Bagur Sonnenahalls. Chikkathirupathi (Post). Malur Taluk. Kolar District

Sir

Sub: Issue of Advice on requirement of fire prevention.

fire fighting & exacuation Measures of Golden International

School Bagur Sonnershalli, Chikkathirupathi (Post),

Malur Taluk, Kolar District -reg.

Ref: Report No 55 RFO/BNG-East/2015 Dated: 07-10-2015.

With reference to the above cited subject, the Regional Fire Officer, Bangalore East Range, Bangalore had from fire prevention, fire fighting & evacuation point of view, inspected the premises of Golden International School, Bagur Sonnenahalli, Chikkathirupathi (Post). Malus Taluk, Kolar District on 13-08-2015 for suggesting fire prevention, fire fighting and evacuation measures. The details are as follows:

A. Details of the Building:-

Address of the premises Golden International School.

Bagur Sonnenahal'i. Chikkathirupathi (Pust)

Malur Taluk. Kolar District.

2. Number of Buildings : One Building.

3. Number of floors : Ground + 2 upper floors - Terrace Floor

4. Ploor wise Details and cours note-

🚨 Clare term, 2.3 Office room

-2-3 Class rooms.

> External structures have been constructed on the terrace floor by using zinc sheet roofing with metal columns. The terrace floor is kept open on all the four sides. The terrace

> floor is been utilized for organizing programmes for the school children's.

5. Height of the Building : 12.19 mtrs.

6. Site area : 2 Acre 27.4 Guta's

7. Built-up area

2nd floor

Terrace Floor

Ground floor : 348.37Sqmtrs.

First Floor : 348.37Sqmtrs.
2nd floor : 348.37Sqmtrs.

8. Type of Constructions : R.C.C. Building.

9. Surroundings.

Front (South) 9.00mtrs internal road via 20.00mtrs wide

Rear (North)

Hosur to white field road.

Onen enges thereoffer 0.00

Rear (North)

Open space thereafter 9.00mtrs wide road.

Open space thereafter 9.00mtrs wide road

Side (West) : Vacant land

10. Name & Address of the : Authorized Signatory

Building Owner. Golden International School,

Bagur Sonnenahalli.
Chikkathirupathi (Post)
Malur Taluk, Kolar District.

11. Name & Address of The Authorized Signatory.
Applicant Golden International School.

Bagur Sonnenahalli, Chikkathiramethi (Post)

Chikkathirapethi (Post) Malur Taluk, Koʻar District.

Marine - Ca

B. On inspection of the school premises, the following fire prevention, fire fighting and evacuation measures are recommended and they are considered absolutely essential:-

	Details (1)	Existing (2)	Recommendations (3)
4 9 2	Approach to the Premises.	The premises is accessible from 9.00mtrs wide internal road via 20.00mtrs wide Hosur to White field road located on the Northern side	The requirement is compiled with
02	Number of entrance	One entrance of 6.00mtrs width from 9.00mtrs wide internal road located on the Southern side.	The requirement is complied with.
03	Number of Staircases	One Staircase of 1.50 mtrs width have been provided	One more staircase of min 1 50 mtrs width shall be provided
()4	Hose Reel Hose	Ant presented	The Hose Reel Hose of 12 man Size and of adequate length to reach the farthest point of each floor, near each staircase shall be provided with a shar off branch having a nozzle of 5mm wire and the hose reel has should be advanted at a farthern hash more reel hose shell be a surrected to an one real tank of 14,4000 liters of posts with at houster pump capable of 1,5 very 450 liters of taget per princts.
	intable Fig.	a National State of the second	

	-4-	CHOOL WAR
(1)	(2)	(3)
06 Fire Prevention measures.	Not indicated	1)Explosive and inflammable materials should not be stored in the premises.
		2)Accumulation of combustible waste in and around the premises should be avoided.
		3)"No smoking" boards shal to be displayed and it shall be strictly prohibited.
ı		4)The stairs, exits, passages etc shall be kept free from obstructions.
07 Escape Route.	Not Marked.	Directions in which the students have to move in the event of any emergency shall be indicated in the corridor on each floor during evacuation.
08 First Aid Box.	Not Provided	One First Aid Box shall be provided at near each staircase) at each floor landing.
09 Fire Order.	Not Displayed.	Notice boards indicating with the details of action to be taken by the employees in case of an emergency /fire shall be displayed near the staircases at each floor with telephone numbers of Hoskote fire Station i.e.27905931, central fire Control room i.e. 22971500, 22971600 & 101 and of nearest Ambulance service.



		-5-	AOLAR DISTIG
go gir ver de	(1)	(2)	(3)
10	Training to employees.	Not imparted	Atleast 40% of the staff should be got trained in fire prevention, fire fighting and evacuation measures at R.A. Mundkur Fire & Emergency Services Academy, Bannerghatta Road, Bangalore.

Under the circumstance stated above, there is No Objection to run Education activities in your school building subject to the condition of providing additional fire fighting equipments and fire precautionary measures shown in column No.3 of part B. Therefore, the school management should comply Karnataka Fire & Emergency Services Department conditions to provide additional equipments and then intimate to this office within 3 months positively without fail. This Fire Advisory Certificate valid for only one year from the date of issue and is renewable.

Yours faithfully

Principar

Golven International School Baguru Sonnenahalli, Malur (Tq) Kolar (**1)

Copy to Regional Fire Officer, Bengrium East Range, Bengalum.

Copy with constantate: Extended to the Digos of Ceneral of Policy of Director Gueral, Karrataka Fire and Tone years Sarrices, Beneature.